final report photos



This photo is facing north taken in the main parking area which was reconfigured and surfaced during this project. The view in the photo shows the new washroom building and main intersection of 6 trails including the main accessible loop as well as the shorter direct link between the field, playground and exercise equipment and the washroom building.

The reclaimed greenspace and new picnic area is in the background of the photo.

photo 1

final report photos



This photo is facing south west at the main intersection of trails or the hub of the park. This view shows a new two sided kiosk, in ground garbage recepticle, new washroom building and the main parking area behind the split rail fence.

The new septic field for the washroom building is in the background beyond the picnic table.

photo 2



This photo is facing north along the new accessible trail where it transects a new picnic area. The arched gateway in the background guides park visitors to the suspension bridge over the Koksilah River.

This reclaimed green space was once a vehicle parking area prior to the BAP Recreation Rejuvenation Project.


photo 3

final report photos



This photo is facing north west along the northern extent of the new accessible trail.

This location is where the old playground once stood. The site was utilized to provide a natural playscape and small amphitheatre/outdoor classroom.



This photo is facing north along the accessible trail loop that connects the playfield to the new nature playscape and amphitheater/outdoor classroom at the western boundary of the park.

The new 2-2.25 metres wide accessible trail is surfaced with compacted angular screenings and an average longitudinal slope of less than 5%.

photo 5

final report photos



This photo is facing north west across the upgraded playfield. This field was regraded providing better drainage and resurfaced with approporiate soil and grass.

The playfield is an unprogrammed recreation area. This field is booked for a variety of recreation and community events.



This photo is facing north towards the new play equipment (background) and shows the intersection bewtween the playground and playfield. Both areas have have received new grass seed and are recovering from excavation.

A total of 13 trees were planted in the playground and exercise equipment area.

final report photos



This photo is facing east on the north side of the playfield looking over the new accessible 2.5 metre wide trail, the 10 exercise stations and the new playground in the background.

New trees and undulating mounds surrounding this area signal a different use and create interesting playful topography around the playground.

photo 8



This photo is facing north on an inner loop of the accessible trail that is shorter route leading directly from the recreation area of the playfield, playground and exercise stations to the washroom building.

final report photos



This photo is facing north on the south edge of the playground. In the background is the accessible trail and 10 exercise stations.

The playground incorporates natural materials and utilizes natural colours to connect to the park surroundings.

final report photos



This photo is facing south above a small Garry Oak restoration area with the new parking lot behind. Cedar split rail fence was used to separate vehicles from the active recreation area. The playground is located to the right where mounding and new trees can be seen.

The new water system is located beyond the building in the background of this image. The utilities are buried along the driveway edge to the new washroom building 150 metres behind this location.

final report photos



This photo is facing west at the intersection of the accessible trail and the park driveway. The spitrail fencing slows pedestrian traffic before reaching the intersection.

The new parking area playground, exercise stations and playfield are in the background.

photo 12



This photo is facing east along the eastern section of the accessible trail. This section passess wetlands that are home to western toads, red legged frogs and Pacific chorus frogs.

This portion of the trail connects the lower parking area to the recreation area where the playground, exercise equipment and playfield are located.

photo 13



This photo is facing north at the new well, water storage and utilities site. The well head and main utilites controls are located in the shed in the background of the image. The water storage necessary for supporting the new washroom building needs (3500 gal) is located underground and accessed through the four valves shown in the photo.

photo 14

final report photos



Initial utilities layout and excavation of upper parking area.



Utilities and connections to well, pump etc..



Ditch along park driveway and laying of utilities.



Drainage ditch adjacent to parking area.

final report photos



Backfilling around water storage tanks.



Washroom building construction.



Preparing new washroom site and utilities connections.



Washroom building construction.

final report photos

ADDITIONAL CONSTRUCTION PHOTOS



Washroom building construction.



Washroom building construction.



Washroom building construction.



Washroom building construction.

final report photos

ADDITIONAL CONSTRUCTION PHOTOS



Clearing bush for trail development.



Accessible trail development.



Accessible trail development.



Accessible trail development.

final report photos



Accessible trail development.



Accessible trail development.



Accessible trail development.



Accessible trail development.

final report photos

ADDITIONAL CONSTRUCTION PHOTOS



Playground development.



Exercise station development.



Playground development.



Exercise station development.

final report photos

ADDITIONAL CONSTRUCTION PHOTOS



Site grading for accessible trail connection.



Hydroseeding adjacent to accessible trail



Site grading and drainage for accessible trail connection.



Temporary irrigation line installation.

final report photos



Concrete and pumper truck placing concrete at outdoor classroom/ amphitheatre



Delivery of trees for playground area.



Formwork, grading and naturescape development.



Initial grading of playfield.

final report photos



Inspection of new septic field.



Hydroseeding on boulevard.



Mounding and grading around playground and exercise stations.



Mounding, grading and grass seeding around playground.